

## MESURES XAPES AW5754

Gruix	Dimensió mm	Pes xapa	H111	H12/22/32
0,5	2000X1000	2,75	-	●
0,6	2000X1000	3,30	●	●
0,6	3000X1250	6,20	-	●
0,8	2000X1000	4,40	●	●
0,8	2500X1250	6,90	●	●
0,8	3000X1500	9,90	●	●
1,0	2000X1000	5,50	●	●
1,0	2500X1250	8,60	●	●
1,0	3000X1250	10,40	●	●
1,0	3000X1500	12,40	●	●
1,2	2000X1000	6,60	●	●
1,2	2500X1250	10,12	●	●
1,2	3000X1250	12,40	●	●
1,2	3000X1500	14,90	●	●
1,5	2000X1000	8,25	●	●
1,5	2500X1250	12,90	●	●
1,5	3000X1250	15,60	●	●
1,5	3000X1500	18,60	●	●
1,5	3000X2000	24,75	●	●
1,5	4000X1250	20,62	●	●
1,5	4000X1500	24,75	●	●
1,5	4000X2000	33,00	●	●
2,0	2000X1000	11,00	●	●
2,0	2500X1250	17,20	●	●
2,0	3000X1250	20,70	●	●
2,0	3000X1500	24,80	●	●
2,0	3000X2000	33,00	●	●
2,0	4000X1250	27,50	●	●
2,0	4000X1500	33,00	●	●
2,0	4000X2000	44,00	●	●
2,5	2000X1000	13,75	●	●
2,5	2500X1250	21,50	●	●

2,5	3000X1500	30,95	●	●
3,0	2000X1000	16,50	●	●
3,0	2500X1250	25,80	●	●
3,0	3000X1250	31,00	●	-
3,0	3000X1500	37,20	●	●
3,0	3000X2000	49,50	●	●
3,0	4000X1250	41,25	●	●
3,0	4000X1500	49,50	●	-
3,0	4000X2000	66,00	●	-
3,0	6000X1500	74,25	-	-
3,0	6000X2000	99,00	●	-
4,0	2000X1000	22,00	●	●
4,0	3000X1250	34,37	●	●
4,0	3000X1500	49,50	●	●
4,0	3000X2000	66,00	●	-
4,0	4000X1500	66,00	●	-
4,0	4000X2000	88,00	●	-
4,0	6000X1500	99,00	●	-
4,0	6000X2000	132,00	●	●
5,0	2000X1000	27,50	●	●
5,0	3000X1250	43,00	●	-
5,0	3000X1500	62,00	●	●
5,0	3000X2000	82,50	●	-
5,0	4000X1500	82,50	●	-
5,0	4000X2000	110,00	●	-
5,0	6000X1500	123,75	●	-
5,0	6000X2000	163,00	●	-
6,0	2000X1000	33,00	●	●
6,0	3000X1250	51,60	●	-
6,0	3000X1500	74,25	●	●
6,0	3000X2000	99,00	●	-
6,0	4000X1500	99,00	●	-
6,0	4000X2000	132,00	●	-
6,0	6000X1500	148,50	●	-
6,0	6000X2000	198,00	●	-

8,0	2000X1000	44,00	●	-
8,0	3000X1250	68,75	●	-
8,0	3000X1500	99,00	●	-
8,0	3000X2000	132,00	●	-
8,0	4000X1500	132,00	●	-
8,0	4000X2000	176,00	●	-
8,0	6000X1500	198,00	●	-
8,0	6000X2000	264,00	●	-
10,0	2000X1000	55,00	●	-

Llegenda: ● Mesura normalitzada  
 - No disponible, consultar